Table 3-7

Recaptured fish with visible injuries after passage through spillbays at Bonneville Dam, October 1995.

				Injury Location and Type				
Location .	· ·	r of Fish Recaptured	Number of Fish with Injuries	Bulging/ Hemorrhaged Eye(s)	Hemorrhaged Gill(s) or Scrape/ Cut on Gill Cover	Scrape/Bruise on Head	Split at Fin(s)	Scrape/Cut/ Bruise on Body
Spillbay 4: Flow Deflector	280	278	5	1	0	1	2	1
Spillbay 2: No Flow Deflector	280	271	6	4	0	0	2	0
Controls for Spillbays	280	269	2	0	1	0	. 0	1
Pooled Spillbay (Treatment)	560	549	11	5	0	1	4	1